

**To:** Scott Smith[ssmith@waterdefense.org]; Grantham, Nancy[Grantham.Nancy@epa.gov]  
**From:** Durno, Mark  
**Sent:** Mon 6/13/2016 5:17:26 PM  
**Subject:** Data and voicemail.

Scott,

Thank you for sending the analytical data from the precipitate that you sampled from Ms. Ex. 6 - Personal Privacy faucet. Below is the feedback from our water experts:

“Pretty much what we thought just looking at it in the photo—mostly calcium phosphate compound from leaking through a worn seal, and Ni no surprise, as it’s a common external plating metal for the finish of faucets. Interior part of faucet probably was brass (Zn, Cu, Pb). The results confirm this is most likely a precipitate of inorganics formed from a small leak at the faucet joint. The mold and aerobic plate count positives do not seem unusual for such a location.”

Also – I got the message you left on my voice mail. We do not have data from them yet. We’ll circle back with you soon on that – when we have the information, we can coordinate a call with Nancy and you.

Mark

---

**Mark Durno**

Homeland Security Advisor / Deputy Chief

Emergency Response Branch  
**U.S. Environmental Protection Agency**  
25063 Center Ridge Road  
Westlake, OH 44145

440-250-1743

